

14" Drill Press

With Laser Function



Δ

WARNING! To Reduce The Risk Of Injury, User Must Read And Understand Instruction Manual.

SP-PB214

FOR SERVICE CALL: 888-896-6881

TABLE OF CONTENTS

RECOGNIZE SAFETY SYMBOLS, WORDS AND LABELS	2
SERVICE	6
SPECIFIC SAFETY RULES AND/OR SYMBOLS	6
PACKAGE CONTENTS	
COMPONENTS	7
ASSEMBLY	9
DPERATION	
MAINTENANCE	12
ACCESSORIES	
FROUBLESHOOTING1	13
PARTS and PARTS LIST	14

RECOGNIZE SAFETY SYMBOLS, WORDS AND LABELS

What You Need to Know About Safety Instructions

Warning and Important Safety Instructions appearing in this manual are not meant to cover all possible conditions and situations that may occur. Common sense, caution and care must be exercised when assembling or using this product.


Always contact your dealer, distributor, service agent or manufacturer about problems or conditions you do not understand.

AWARNING This is a safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

CAUTION

This is a safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

GENERAL PRODUCT SPECIFICATIONS



FFATURES:

- · Enclosed Fan Cooled Motor
- Belt Drive Speed Adjustment
- Rack & Pinion Table Raises And Lowers Easily
- · Cast Iron Table, Base And Drill Body
- 11-3/8" Diameter Dry Round Table Tilts 90 Degrees Left & Right

SPECIFICATIONS

· Rated Current 6.6 AMP / 550 Watt · Rated Voltage 120V / 60 Hz Max Speed 210-3.840 RPM

 Chuck Capacity 5/8" 3/4 HP Motor Laser class 2

KEEP THIS MANUAL, SALES RECEIPT & APPLICABLE WARRANTY FOR FUTURE REFERENCE. READ ALL INSTRUCTIONS AND WARNINGS BEFORE USING THIS PRODUCT.

FOR CONSUMER USE ONLY - NOT FOR PROFESSIONAL USE

Owner's Manual

IMPORTANT SAFETY RULES

COMMON SENSE AND CAUTION ARE FACTORS WHICH CANNOT BE BUILT INTO ANY PRODUCT. THESE FACTORS MUST BE SUPPLIED BY THE OPERATOR.

A WARNING

Keep your work area clean and well lit.

Cluttered work benches and dark work areas may cause accidents or injury.

Do not operate drill in explosive areas, such as in the presence of flammable liquids, gases or dust. The drill may create sparks which may ignite the dust or fumes.

Keep bystanders, children & visitors away while operating the drill.

Distractions can cause you to lose control.

▲ WARNING

Double insulated tools are equipped with a polarized plug (one blade is wider than the other.) This plug will fit in a polarized outlet only one way. If the plug does not fit fully in the outlet. reverse the plug. If it still does not fit, contact a qualified electrician to install a polarized outlet. Do not change the plug in any way. Double insulation eliminates the need for the three wire

grounded power cord and grounded power supply system.

Avoid body contact with grounded surfaces such as pipes, radiators, ranges and refrigerators.

There is an increased risk of electric shock if your body is grounded.

Do not abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet. Keep the cord away from heat, oil, sharp edges, or moving parts. Replace damaged cords immediately. Damaged cords increase the risk of electric shock.

When operating the tool outside, use an outdoor extension cord marked "WA" or "W." These cords are rated for outdoor use and reduce the risk of electric shock. Make sure the extension cord being used is in good condition. If there are any cuts or nicks (no matter how deep) in the insulation. DO NOT use that cord. Also, make sure the extension cord is heavy enough to carry the current needed. DO NOT use small "around-the-house" lamp extension cords.

These cords can easily overheat and/or catch fire when used with power tools.

A CAUTION

Do not force tool. Use the correct tool for your application.

The correct tool will do the job better and safer at the rate for which it is designed.

Do not use the tool if the power switch does not turn it "ON" or "OFF".

Any tool that cannot be controlled with the switch is dangerous and must be repaired.

Disconnect the power cord plug from the power source before making any adjustments, changing accessories or storing the tool.

Such preventive safety measures reduce the risk of starting the tool accidentally. Store idle tools out of reach of children and other untrained persons.

Tools are dangerous in the hands of untrained users.

▲ DANGER

People with pacemakers or other electronic devices should consult with a physician before operating this product. Interruption or failure of the pacemaker could occur when electrical equipment is operated within close proximity of electrical devices.

▲ WARNING

Wash hands after handling the power cord. Touching the power cord could expose you to lead, which is known in the State of California to cause cancer, birth defects and other reproductive harm.

▲ WARNING

All work areas should be clean and well lit.

Accidents are more likely to occur in poorly lit and cluttered areas.

AWARNING

Keep children, and other distractions at a distance while operating power tools.

AWARNING

Keep the power cord in good condition, and replace damaged cords immediately. Do not use the cord to pull the plug from the outlet. Keep the cord away from materials and surfaces that could damage cords. The risk of electric shock increases when the power cord is damaged.

A WARNING

Always use the appropriate extension cord, making sure it is rated for use with drills. Always be sure the extension cords are in good condition, free of cuts or nicks in the insulation. If using the drill in an outside area with an extension cord, make sure the cord is rated for outdoor use.

A WARNING

Do not make contact with a grounded surface while using this power tool.

Contact with surfaces like pipes, radiators or major appliances increases your risk of electric shock.

A WARNING

Use common sense while operating this drill.

Do not use this drill if you are:

Feeling tired or are under the influence of alcohol or drugs.

Wearing loose clothing or jewelry. Keep long hair pulled back and away from moving parts. Overreaching or have improper footing. Handling the tool in this way could cause serious injury. When using this drill always:

- Wear the proper safety equipment, such as safety goggles, dust masks, non-skid shoes, etc.
- Be sure all adjusting keys or wrenches have been removed before starting the drill.

A CAUTION

Follow these steps to maintain safe working conditions and good working condition of power tools. Improper care can result in electric shock or serious injury.

- Secure and support the work piece using clamps. Do not use your hands to hold the piece in place.
- Use the correct tool for the job. Using the correct tool is safer and faster.
- Make sure the power switch is in good working order. If the power switch no longer turns the tool "ON" or "OFF", discontinue use, and have the tool replaced or repaired.
- Remove the power cord from the power source before storage, changing accessories, or moving the tool.
- Keep out of reach of children, or any untrained person. Store tools in a safe and dry place.
- Keep tools clean, and cutting tools sharp. Maintaining tools with proper care will increase the life of the power tool, and reduce the risk of injury.
- Check to be sure all moving parts are free from binding and are properly aligned.
- Use only accessories that are recommended by the manufacturer for your tool model.

▲ WARNING

Safety glasses and ear protection must be worn during operation.



ALWAYS WEAR EYE PROTECTION.

A drill press can throw foreign objects into your eyes which could cause permanent eye damage.

ALWAYS wear safety goggles (not glasses). Ordinary eyeglasses have only impact-resistant lenses...they ARE NOT safety goggles.

Owner's Manual

SERVICE

Tool service must be performed only by qualified repair personnel.

Service or maintenance by unqualified personnel could result in a risk of injury.

When servicing a tool, use only identical replacement parts and follow instructions in the manual. Use of unauthorized parts or failure to follow maintenance Instructions may create a risk of shock or iniury.

SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE.

This manual contains important information regarding safety, operation, maintenance and storage of this product. Before use, read carefully and understand all warnings, cautions, instructions and labels. Failure to do so could result in serious personal injury, property damage or even death.

IMPORTANT SAFETY INSTRUCTIONS

A WARNING

Before using this tool, you need to become familiar with its operation. If you are unsure about the operation of the tool, or have any questions about its proper use, call the Customer Service Department at 888-896-6881. Follow these instructions for safe handling of the tool:

- Always secure and support the work piece using clamps. Do not use your hands to hold the piece in place.
- Be sure your work area is clean and secure before turning the power switch into the "ON" position. Be sure the area is free from all foreign material, nails, staples, or any other material.
- Turn the drill "OFF" and unplug from the power source before making any changes or adjustments to the drill.
- Do not use solvents containing carbon tetrachloride, ammonia or acetone to clean the drill. Never use gasoline, paint thinner, or other caustic chemicals that can damage the plastic parts of
- Always use the appropriate safety gear when operating this drill. Including but not limited, to googles, dust mask or respirator. Always work in a well-ventilated area to reduce your exposure to harmful chemicals and dust particles.
- Keep hands away from the cutting area.
- · Do not reach under the work piece.

SPECIFIC SAFETY RULES AND/OR SYMBOLS

The following symbols may be used on your tool. Be familiar with and learn the symbols to operate the tool safely.

Symbol	Name	Description		
V Volts		Voltage (Potential)		
A	Amperes	Current		
Hz	Hertz	Frequency (Cycles per Second)		
W	Watt	Power		
Kg	Kilograms	Weight		
\sim	Alternating Current	Type of Current		
	Direct Current	Type of Current		
$\overline{\sim}$	Alternating or Direct Current	Type of Current		
働	Earthing Terminal	Grounding Terminal		
	Class II Construction	Denotes Double Insulation		
min	Minutes	Time		
S	Seconds	Time		
Ф	Diameter	Size of Drill Bits, Grinding Wheels, etc.		
$n_{_{0}}$	No Load Speed	No-load Rotational Speed		
/min	Revolutions per Minute	Revolutions,Surface Speed, Strokes, etc. per Minute		
1,2,3 Ring Selector Settings		Speed, Torque or Position Settings		


PACKAGE CONTENTS

- 16 Speed Drill Head Assembly
- Table Assembly
- Base
- Column Assembly
- Chuck Guard Assembly
- Assorted loose parts

COMPONENTS

- 1) Quill Feed Spring Adjustment
- 2) Column
- 3) Feed Handle
- 4) Power Switch
- 5) Laser Light Switch
- 6) Rack
- 7) Base
- 8) Table
- 9) Column Support
- 10) Arm Locking Handle
- 11) Table Lock


ASSORTED LOOSE PARTS



10

Owner's Manual

PARTS DESCRIPTION



ASSEMBLY

AWARNING

Do not stare directly at the laser beam. Never aim the beam at any person or object other than the work piece. Do not deliberately aim the beam at personnel. Staring at the beam may cause flash blindness.

NOTE

Unpack product from package and review contents. Keep all packaging until product has been reviewed

Do not operate the machine until it is completely assembled.

Make sure the proper electrical regulations are followed, and that the machine is properly grounded. Before switching the machine ON, ALWAYS: a. Make sure all chuck keys, spanners and wrenches are removed from the machine. b. Examine the setup carefully, making certain that the workpiece is perfectly secure. c. Make sure your clothing is properly adjusted.

Make all adjustments with the power OFF.

Always use the correct drilling speeds for the drill size, and the type of material being drilled. NEVER leave the drill unattended while it is running. Turn the machine OFF and do not leave until it has come to a complete stop. When you have finished with the machine, always remove and store the drill bits. CAUTION: This Drill Press is designed for use with Drill Bits and Mortising attachments ONLY.

The use of other cutting tools or accessories could be hazardous. ALWAYS use clamps, or a drill vise bolted to the table, to hold the work. It should NEVER be held in bare hands.

Using the Laser

The laser light/laser radiation used in this laser centering device system is Class 2 with maximum 1mW and 400nm - 700nm wavelengths. These lasers do not normally present an optical hazard, although staring at the beam may cause flash blindness.

Changing the Batteries

Unclip the battery cover to gain access to the batteries. Replace both AA batteries, taking care to insert the new batteries with the correct polarity.

Use only 2 AA batteries. DO NOT mix old and new batteries. DO NOT mix alkaline, standard (carbon -zinc) or rechargeable (nickel-cadmium) batteries.

Replace the laser light battery cover and make certain that the light is not directed towards the eye of a person. Always make sure that the laser beam is aimed at a sturdy work piece without reflective surfaces, i.e. wood or rough surfaces are acceptable. Bright, shiny, reflective sheet steel or the like is not suitable for laser use, as the reflective surface could direct the beam back at the operator. Only turn the laser beam on after the work piece is in place. CAUTION: Remove the laser light batteries when tool is to be stored without use for a few days.

Resetting the Laser Beam

Loosen the set screw on each of the laser tubes and adjust the tubes until the two beams intersect at the point where the drill bit touches the work piece. Retighten the set screws more. If left in position, the batteries might leak and damage the laser light assembly. Damage caused by battery leakage is not covered under warranty.

Owner's Manual

Column Assembly to Base

NOTE: Ideally, the base should be firmly bolted to the floor, prior to assembly of other components. The mounting surface must be flat, level and capable of supporting the drill weight.

With the base on a flat level surface, bolt on the Column using the 4.M10 Hex head screws provided and tighten. Carefully locate the table in its support and tighten up with the table locking handle. Check to make sure the column securing set screws, at the column support, are tight. Fit the crank to the shaft on the crank assembly.

Head to Column

NOTE: It may be necessary to unscrew the Head Lock Set Screws slightly to make sure they do not protrude internally as this would prevent the head from sliding fully into position. 1. Raise the head and locate it on top of the column. 2. Align the head with the base and firmly secure with the set screws using the wrench. Locate the three feed handles and screw them into the hub of the spindle feed shaft.

Chuck Guard Assembly

NOTE: This operation should be carried out before the chuck is installed. Slide the Chuck Guard over the Quill shaft, turn it so that the pinch bolt faces the front, then tighten up the pinch bolt to temporarily secure it in this position. IMPORTANT Make sure the Quill Shaft Spindle is at the top of its travel.

Pulley Cover Knob

Locate the knob, with pan head screw and attach to the cover, screwing on tightly.

Installing the Chuck

- 1. Slide the table up the column and secure it to within 6"of the spindle.
- 2. Open the jaws of the chuck to their maximum, using the chuck key supplied.
- 3. Put a piece of scrap wood on to the table to protect the chuck nose.
- 4. Make sure all parts are thoroughly clean, dry, and burr free. Place the chuck over the end of the arbor and pull the spindle down using the feed handles, pressing the chuck jaws hard against the piece of scrap wood until the chuck is securely in place.
- 5. Turn Chuck Guard 180 degrees and tighten Lock Set Screws slightly to make sure pinch bolt.

Fitting the Drive Belts

Undo the Belt Tension Locking Screws (one on either side of the head) and turn the Belt Tension Lever clockwise to bring the Motor Pulley closer to the Spindle Pulley (which will allow the belts to be slipped on with ease).

Lightly grease the idler pulley pivot shaft and locate the idler pulley assembly in its' mounting between the Motor and spindle Pulleys. Consult the chart inside the belt cover, and fit the belts in the position corresponding to spindle/drill speed required.

Turn the Belt Tension Lever counter-clockwise so that tension is applied to the belts. Tension is correct when the belts deflect by approx. 1/2" at their centers of run when using reasonable thumb pressure. Lock the motor in the position with the Belt Tension Locking Screws. 1. The idler pulley will 'float' so that tension is applied equally to both belts 2. If the belt should slip while drilling, adjust the belt tension.

ASSEMBLY

SETTINGS AND ADJUSTMENTS

The table may be raised, lowered or swivelled about the column, by loosening the table support locking handle (Fig.8). Adjust accordingly using the table crank, and re-tighten the locking handle. If the table assembly moves stiffly when being swivelled about the column, loosen the upper collar allen screw (at the rack) to allow the collar to move very slightly, thereby providing a little more clearance between rack and collar. Tighten the allen screw when satisfied. The table may also be turned on its axis by loosening the pinch bolt at its' mounting shaft.

Spindle Depth

Located around the spindle feed shaft is a Depth Stop Collar, printed with a graduated scale. The collar is capable of turning about the shaft and may be locked in place by the locking screw. The scale is printed in both inches and metric. To set a drilling depth: 1. With the power OFF, lower the drill bit so that it contacts the work, and hold in that position. 2. Loosen the locking screw and turn the collar so that the measurement for the depth of hole required is in line with the pointer (C). Lock the collar in this position using the locking screw. The drill is now set to drill holes to your predetermined depth. from that particular start point.

Changing Drill Speed

Before changing the speed, make sure the machine is switched OFF, and unplugged. Undo the Belt Tension Locking Screws on either side of the head and turn lever clockwise to relieve any tension on the belts. Refer to the chart inside the belt cover install the belts in the positions corresponding to the spindle speed required. Level the motor, on its bracket, away from the head, by turning lever counter clockwise so that tension is applied to the belts.

NOTE: The idler pulley will 'float' so that tension is equally applied to both belts. Tension is correct when the belts deflect by approx. 1/2" at their center when using reasonable thumb pressure. Lock the motor in this position using the two locking screws. If the belt should slip while drilling, adjust the belt tension,

OPERATION

A CAUTION

Wear safety eyewear and dust filters or respirators while using this tool.

Insert the drill bit into the jaws of the chuck by approximately 1". Be certain that the jaws do not touch the flutes of the drill. Before tightening the chuck, make sure that the drill bit is centered within the jaws. Make sure the table height and position is set so that drill travel is sufficient for the job in hand.

Make sure the work is securely clamped, or held in a drill vise bolted to the table. Never hold it with bare hands. Severe personal injury may be caused if the workpiece is forced out of the operator's hand, and damage to the machine incurred if the work strikes the column. If the piece is of irregular shape and cannot be laid flat on the table, it should be securely blocked and clamped. Any tilting, twisting or shifting, results not only in a rough hole, but also increases drill bit breakage.

For small workpieces that cannot be clamped to the table, use a Drill Press Vise. The vise must be clamped or bolted to the table. When drilling completely through wood, always position a piece of scrap wood between the workpiece and the table to prevent splintering on the underside of the workpiece as the drill breaks through. The scrap piece of wood must make contact with the left side of the column. In addition, set the depth of drill travel so that the drill cannot possibly come into contact with the table, or, align the table so that the center hole is directly in line with the drill bit. When completely satisfied that the setup is sound, lower the Chuck Guard into place, and switch the machine ON.

Owner's Manual

Insert KEY into switch. Key is made of yellow plastic. A light is also provided which is built into the head. The light switch is located above the ON/OFF switch.

REMOVING THE CHUCK

To remove the chuck, pull the spindle down fully, using the feed handles. The slot in the side of the Quill will become visible. Note the position of the chuck, perhaps by placing a chalk mark, in line with the chuck, on the column, then raise the table so that it is only an inch or so below the position marked.

Place a thick cloth, or similar material, on the table to catch the chuck, to prevent damage when it drops. Pull down the spindle once more, until the slot in the Quill tube is visible. Insert the drift wedge into the slot and give it a sharp tap, preferably with a copper hammer. This will break the seal between the guill tube and the arbor, allowing the chuck to fall free, on to the cloth on the table. To disconnect the chuck from the arbor, give it a sharp rap with a soft head mallet to break the taper seal.

NOTE: Morse taper drills (MTS), may also be used with this machine, and are inserted into the Quill to replace the arbor. Removal is the same as that for removing the chuck.

MAINTENANCE

▲ WARNING

Disconnect the power supply before cleaning. Wear safety eyewear before cleaning. Used compressed dry air to blow off dust and debris. Use a soft bristle brush if compressed air is not available.

CAUTION

Applying excessive force to the tool can overload the motor, decrease the life and increase the wear on the tool.

CAUTION

Some chemicals can damage the product. Do not use harsh chemicals such as gasoline, carbon tetrachloride, paint thinner, etc.

CAUTION

A qualified repair technician must perform any tool service or repair. Service or maintenance performed by unqualified personnel could result in injury. Use only identical replacement parts, Use of unauthorized parts or failure to follow maintenance instructions may create a risk of electric shock or injury.

▲ WARNING

Do not make contact with a grounded surface while using drill press.

Contact with surfaces like pipes, radiators or major appliances increase your risk of electric shock.

The Drill Press must be properly maintained for maximum performance. Always inspect before use. Any damage should be repaired, and faults rectified. Please refer to the troubleshooting chart. If you are unable to correct any problems, please contact customer service.

Monthly (When in constant use)

- 1. Check tightness of mounting bolts, and head and column securing set screws.
 2. Check belt for wear and replace if frayed or damaged in any way.
- 3. Blow out any dust that may have accumulated in the motor fan.
- 4. Apply a thin coat of wax paste or light oil to the table and column for lubrication and to help prevent corrósion.

Lubrication

All bearings are packed with grease at the factory and require no further lubrication. After use, remove all swarf from the machine and thoroughly clean all surfaces. Components should be dry, with machined surfaces lightly oiled. Always remove drill bits, and store in a safe place.

ACCESSORIES

Use only accessories that are recommended by the manufacturer for your model. Accessories that may be suitable for one tool may become hazardous when used on another tool.

Always attach grounded (3-prong) extension cords to grounded (3-prong) outlets.

If you must use an extension cord, be sure that the gauge is large enough to carry the amount of current necessary for your power tool. If not, your tool may experience a loss of power, excessive voltage drop or overheating. For example, the smaller the gauge number, the heavier the cord.

TROUBLESHOOTING

Noisy? Review the probable cause and remedy:

A) Incorrect belt tension

A) Adjust tension operation

B) Dry spindle

B) Remove spindle / quill assembly and lubricate

C) Loose pulley lubricate

C) Tighten Pulley

D) Worn bearing

D) Replace bearing

Excessive drill wobble? Review the probable cause and remedy:

A) Loose chuck

A) Tighten by pressing chuck down on to a block of wood against the table.

B) Worn spindle or bearing

B) Replace spindle shaft or bearing

C) Worn chuck

C) Replace chuck

D) Bent drill bit

D) Replace drill bit

Motor won't start? Review the probable cause and remedy:

A) Power supply

A) Check power cord/fuse start B) Check motor connections

B) Motor connection C) NVR switch connections

D) Faulty Switch

C) Check switch connections D) Replace switch

E) Motor Windings Burned

E) Replace Motor

Drill Bit Binds in Workpiece? Review the probable cause and remedy:

A) Excessive Feed Pressure

A) Apply less pressure B) Check Belt tension

B) Loose Belt

C) Tighten drill bit with key

C) Loose Drill Bit D) Incorrect drill speed


D) Refer to Cutting Speed chart, and adjust drill speed accordingly

Table difficult to raise? Review the probable cause and remedy: A) Needs lubrication

A) Lubricate with light oil


B) Table lock tightened B) Loosen clamp

Owner's Manual



AI A I GILO NO.	140.	Description
PB214-01-HY	01	Knob
PB214-02-HY	02	Operating handle
PB214-03-HY	03	Handle holder
PB214-04-HY	04	Gear shaft
PB214-05-HY	05	Depth scale label
PB214-06-HY	06	Scale label ring
PB214-07-HY	07	Depth setting knob
PB214-08-HY	08	Rivet
PB214-09-HY	09	Depth pointer
PB214-10-HY	10	Laser guide
PB214-11-HY	11	Teeth washer
PB214-12-HY	12	Earth terminal
PB214-13-HY	13	Elastic washer
PB214-14-HY	14	Screw
PB214-15-HY	15	Switch box
PB214-16-HY	16	Switch box plate
PB214-17-HY	17	Switch
PB214-18-HY	18	Work light switch
PB214-19-HY	19	Screw
PB214-20-HY	20	Screw
PB214-21-HY	21	Flat washer
PB214-22-HY	22	Nut
PB214-23-HY	23	Screw
PB214-24-HY	24	Spring
PB214-25-HY	25	Spring cap
PB214-26-HY	26	Nut
PB214-27-HY	27	Laser guider switch
PB214-28-HY	28	Battery box cover
PB214-29-HY	29	Battery box
PB214-30-HY	30	Screw


APA Parts No.	No.	Description
PB214-31-HY	31	Battery
PB214-32-HY	32	Electric polarity
PB214-33-HY	33	Cable clamping plate
PB214-34-HY	34	Screw
PB214-35-HY	35	Cable and plug
PB214-36-HY	36	Allen key
PB214-37-HY	37	Allen key
PB214-38-HY	38	Fixing bracket for light holder
PB214-39-HY	39	Light holder
PB214-40-HY	40	Screw
PB214-41-HY	41	Cylinder pin
PB214-42-HY	42	Machine body
PB214-43-HY	43	Belt tension adjusting handle
PB214-44-HY	44	Screw
PB214-45-HY	45	Motor supporting bar
PB214-46-HY	46	Key
PB214-47-HY	47	Adjusting lever
PB214-48-HY	48	Screw
PB214-49-HY	49	Bolt
PB214-50-HY	50	Elastic washer
PB214-51-HY	51	Flat washer
PB214-52-HY	52	Flat washer
PB214-53-HY	53	Motor base
PB214-54-HY	54	Elastic washer
PB214-55-HY	55	Nut
PB214-56-HY	56	Motor
PB214-57-HY	57	Motor pulley
PB214-58-HY	58	Screw
PB214-59-HY	59	Nut
PB214-60-HY	60	



APA Parts No.	No.	Description
PB214-01-HY	01	Base
PB214-02-HY	02	Flat washer
PB214-03-HY	03	Elastic washer
PB214-04-HY	04	Bolt
PB214-05-HY	05	Screw
PB214-06-HY	06	Column holder
PB214-07-HY	07	Rack
PB214-08-HY	08	Column
PB214-09-HY	09	Column collar
PB214-10-HY	10	Work table
PB214-11-HY	11	Bolt
PB214-12-HY	12	Elastic washer

-	Jan 21	
APA Parts No.	No.	Description
PB214-13-HY	13	Screw
PB214-14-HY	14	Table holder
PB214-15-HY	15	Locking handle
PB214-16-HY	16	Zero scale label
PB214-17-HY	17	Angle scale label
PB214-18-HY	18	Rivet
PB214-19-HY	19	Table support
PB214-20-HY	20	Gear
PB214-21-HY	21	Gear pin
PB214-22-HY	22	Worm
PB214-23-HY	23	Screw
PB214-24-HY	24	Crank

PULLEY AND SPINDLE ASSEMBLY DIAGRAM



PULLEY AND SPINDLE ASSEMBLY PARTS LIST

APA Parts No.	No.	Description	APA Parts No.	No.	Description
PB214-01-HY	01	Retaining ring	PB214-17-HY	17	Ball bearing
PB214-02-HY	02	Ball bearing	PB214-18-HY	18	Spacer
PB214-03-HY	03	V-belt	PB214-19-HY	19	Retaining ring
PB214-04-HY	04	Middle pulley	PB214-20-HY	20	Pulley insert
PB214-05-HY	05	ldle bracket	PB214-21-HY	21	Spindle pulley
PB214-06-HY	06	Pulley cover	PB214-22-HY	22	Nut
PB214-07-HY	07	Rubber ring	PB214-23-HY	23	E-ring
PB214-08-HY	08	Rubber pad	PB214-24-HY	24	Ball bearing
PB214-09-HY	09	Nut	PB214-25-HY	25	Rubber washer
PB214-10-HY	10	Flat washer	PB214-26-HY	26	Spindle quill
PB214-12-HY	12	Screw	PB214-27-HY	27	Wedge key
PB214-11-HY	11	Cable clamping plate	PB214-28-HY	28	Ball bearing
PB214-13-HY	13	Screw	PB214-29-HY	29	Spindle
PB214-14-HY	14	Flat washer	PB214-30-HY	30	Arbor
PB214-15-HY	15	Knob	PB214-31-HY	31	Chuck
PB214-16-HY	16	Retaining ring	PB214-32-HY	32	Chuck key
		·			

Limited Warranty

Steele® warrants to the original purchaser who uses the product in a consumer application (personal, residential or household usage) that all products covered under this warranty are free from defects in material and workmanship for one year from the date of purchase. All products covered by this limited warranty which are used in commercial applications (i.e. income producing) are warranted to be free of defects in material and workmanship for 90 days from the date of original purchase. Products covered under this warranty include air compressors, tools, service parts, pressure washers and generators.

Steele® will repair or replace, at Steele®'s sole option, products or components which have failed within the warranty period. Service will be scheduled according to the normal work flow and business hours at the service center location, and the availability of replacement parts. All decisions of Steele® with regard to this limited warranty shall be final.

This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

RESPONSIBILITY OF ORIGINAL PURCHASER (initial User):

To process a warranty claim on this product, DO NOT return item to the retailer. The product must be evaluated by an Authorized Warranty Service Center. For the location of the nearest Authorized Warranty Service Center contact the retailer or place of purchase.

Retain original cash register sales receipt as proof of purchase for warranty to work.

Use reasonable care in the operation and maintenance of the product as described in the Owner's Manual(s).

Deliver or ship the product to the Authorized Warranty Service Center. Freight costs, if any must be paid by the purchaser. If the purchaser does not receive satisfactory results form the Authorized Warranty Service Center, the purchaser should contact Steele® toll free 888-896-6881.

THIS WARRANTY DOES NOT COVER:

Merchandise sold as reconditioned, used as rental equipment, or floor or display models.

Merchandise that has become damaged or inoperative because of ordinary wear, misuse, cold, heat, rain, excessive humidity, freeze damage, use of improper chemicals, negligence, accident, failure to operate the product in accordance with the instructions provided in the Owner's Manual(s) supplied with the product, improper maintenance, the use of accessories or attachments not recommended by Steele®, or unauthorized repair or alterations.

- Repair and transportation costs of merchandise determine not to be defective.
- Costs associated with assembly, required oil, adjustments or other installation and start-up costs. Expendable parts or accessories supplied with the product which are expected to become inoperative or unusable after a reasonable period of use.

Merchandise sold by Steele® which has been manufactured by and identified as the product of another company, such as gasoline engines. The product manufacturer's warranty, if any, will apply.

ANY INCIDENTAL, INDIRECT OR CONSEQUENTIAL LOSS, DAMAGE, OR EXPENSE THAT MAY RESULT FROM ANY DEFECTS, FAILURE OR MALFUNCTION OF THE PRODUCT IS NOT COVERED BY THIS WARRANTY. Some states do not allow the exclusion, so it may not apply to you.

IMPLIED WARRANTIES, INCLUDING THOSE OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, ARE LIMITED TO ONE YEAR FROM THE DATE OF ORIGINAL PURCHASE. Some states do not allow limitations on how long an implied warranty lasts, so the above limitations may not apply to you.

Distributed by: 730 S.Epperson Dr. City Of Industry,CA91748 www.steele-products.com all rights reserved